## National Transportation Safety Board NTSB ID: DEN02LA029 Aircraft Registration Number: N434QS FACTUAL REPORT Occurrence Date: 02/08/2002 Most Critical Injury: Serious Occurrence Type: Accident Investigated By: NTSB Location/Time Nearest City/Place State Zip Code Local Time Time Zone CO 80021 1126 **MST** Broomfield Distance From Landing Facility: Direction From Airport: Airport Proximity: Off Airport/Airstrip Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft Gulfstream Aerospace G-IV Airplane Sightseeing Flight: No Air Medical Transport Flight: No

## Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On February 8, 2002, at 1126 mountain standard time, N434QS, a Gulfstream Aerospace G-IV, operated by Executive Jet International of Bluffton, South Carolina, was not damaged when it encountered turbulence while descending en route to BJC, Jefferson County Airport (Jeffco), Broomfield, Colorado. There were no injuries to the airline transport captain and first officer and one passenger, but the flight attendant did sustain a serious injury. Visual meteorological conditions prevailed, and an IFR flight plan had been filed for the corporate flight being conducted under Title 14 CFR Part 91. The flight originated at San Jose, California, at 0825 Pacific standard time.

According to Federal Aviation Administration documents, the Denver Air Route Traffic Control Center (ARTCC) advised the flight crew of possible severe turbulence over TOMSN intersection at Flight Level (FL) 190 (TOMSN intersection is located approximately 31 nautical miles north-northwest of Jeffco Airport). According to the captain's written statement, as the airplane descended on the TOMSN 3 STAR (Standard Terminal Arrival Route), she checked BJC's ATIS (Automated Terminal Information Service) that advised of moderate turbulence below 10,000 feet msl. She briefed the flight attendant that turbulence was possible at lower altitudes, and that he should be seated and restrained if the "Fasten Seatbelt/No Smoking" sign was to illuminate. As the airplane vacated FL 250, ARTCC advised the crew of possible severe turbulence over TOMSN intersection and to stop its descent at FL 210. The captain turned on the "Fasten Seatbelt/No Smoking" sign. Shortly thereafter, as the airplane passed FL 220, the airplane encountered "severe turbulence" that lasted until the airplane reached about 3,000 feet (above ground level). She heard the flight attendant screaming, but was unable to check him because of more demanding flight duties. The pilot asked ARTCC for priority handling to the airport, and to have emergency equipment standing by. The flight attendant was taken to a local hospital where X-rays revealed he had fractured a bone in his ankle.

The flight attendant later told the captain that prior to encountering the turbulence, he had left his seat to retrieve a lint brush from the galley for the passenger. He heard the "Fasten Seatbelt/No Smoking" chime and returned to his seat. The airplane encountered the turbulence before he could fasten his seatbelt and he was thrown about, landing on his ankle.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN02LA029

Occurrence Date: 02/08/2002

AVIATION		Occurrence Type: Accident											
Landing Facility/Approach In	formation	•											
Airport Name	Airport ID:	Airpo	ort Elevation	Run	way Used	Runwa	ay Lengt	h	Runv	vay Width			
Jeffco			BJC		Ft. MSL								
Runway Surface Type: Unknown													
Runway Surface Condition: Unkno	own												
Type Instrument Approach: Unknown	own												
VFR Approach/Landing: Unknown	า												
Aircraft Information													
Aircraft Manufacturer				l/Series						Number			
Gulfstream Aerospace			G-IV						1334				
Airworthiness Certificate(s): Trans	sport												
Landing Gear Type: Retractable	- Tricycle												
Homebuilt Aircraft? No	Number of Seats:	ber of Seats: 16 Certified Max Gross Wt. 73200 LBS Number						er of En	of Engines: 2				
•				Engine Manufacturer: Model/Series: 611-8 TAY								ed Power: 350 LBS	
- Aircraft Inspection Information													
Type of Last Inspection			Date of Last Inspection Time			Time Si	me Since Last Inspection				Airframe Total Time		
AAIP			11/2001			340 Hours				3329 Hours			
- Emergency Locator Transmitter (	ELT) Information												
ELT Installed? Yes	ELT Operate	ed? No			ELT	Aided i	in Locating Ac	cident S	ite? No	)			
Owner/Operator Information													
Registered Aircraft Owner			Street /	Address		Cross R	d Suite 200	)					
Executive Jet International			City									Zip Code	
					luffton					SC		29910	
Operator of Aircraft			Street A			'd Aircr	aft Owner						
Same as Reg'd Aircraft Owner				Same as Reg'd Aircraft Owner City						Stat	е	Zip Code	
Operator Does Business As:  Operator Designator Code:													
- Type of U.S. Certificate(s) Held: None													
Air Carrier Operating Certificate(s)	:												
Operating Contificates					aratar Cartifi	noto:							
Operating Certificate:	Part Q1: Capara	al Avioti	ion	Lob	perator Certific	Jaie.							
Regulation Flight Conducted Unde			UII										
Type of Flight Operation Conducted	J. Executive/Corp	orate											
	]	FACTU	JAL REPO	ORT - A	AVIATION							Page 2	

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN02LA029

Occurrence Date: 02/08/2002

AVIATI AVIATI	Occurrence Type: Accident											
First Pilot Information												
Name	City			State Da		ate of Birth	Age					
On File	On File	ile			) O	n File	54					
Sex: F Seat Occupied	: Left	Prir	ncipal Profes	n Pilot	ot Certificate Number: On File							
Certificate(s): Airline Transport												
Airplane Rating(s): Multi-engine Land; Single-engine Land												
Rotorcraft/Glider/LTA: None												
Instrument Rating(s): Airp	lane											
Instructor Rating(s): None												
Type Rating/Endorsement for	or Accident/In	cident Aircra	ft? Yes		(	Current Bier	nial Flight R	eview?	11/200	)1		
Medical Cert.: Class 1	Medica	l Cert. Status	S: Valid Med	dicalw/ wa	ivers/lim.		Date of La	ast Medic	al Exa	m: 10/2001		
- Flight Time Matrix  All A/C  This Make and Model			Airplane Single Engine	Airplane Mult-Engine	Night	Inst Actual	ument Simulated	Rotor	craft	Glider	Lighter Than Air	
Total Time	9862	3005	1080	8782	998	25°	24	0				
Pilot In Command(PIC)	9498	2117	903	5595	620	18	24	0				
Instructor								_				
Last 90 Days	153 60	153 60		153 60	41 17	13						
Last 30 Days Last 24 Hours	60	60		60	17	<del>                                     </del>	<u>-                                    </u>	+				
Seatbelt Used? Yes	Shou	Ider Harness	Used? Yes		Toxic	ology Perfo	rmed? No		Seco	ond Pilot? Ye	s	
Flight Plan/Itinerary												
Type of Flight Plan Filed: IF	R											
Departure Point					State	State Airport Identi		ifier Departur		re Time	Time Zone	
San Jose					CA	CA SJC		0825			PST	
Destination					State	e Air	oort Identifie	er				
Broomfield CO							BJC					
Type of Clearance: IFR												
Type of Airspace: Class A												
Weather Information												
Source of Briefing:  Company												
Method of Briefing: Telephone												
FACTUAL REPORT - AVIATION Page 3												

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN02LA029

Occurrence Date: 02/08/2002

Occurrence Type: Accident

	PETYBOR		1 000	unchice	турс.	Acciden	ι						
Weather	Information												
WOF ID	Observation Time	Time Zone	WOF E	Elevation	n	WOF Distance From Accident Site				Direction From Accident Site			
DEN	1053	MST	543	31 Ft. N	1SL	21 NM				265 Deg. Mag.			
Sky/Lowes	st Cloud Condition: Scatt					12000 Ft. AGL			Condition of Light: Day				
Lowest Ce	iling: Broken	2000	20000 Ft. AGL		Visibi	lity:	10	SM	Altimeter:		29.76	"Hg	
Temperatu	ıre: 11 °C	Dew Point:	-16	s °C	Wind [	Direction:	300		Density Altitude:			6382	Ft.
Wind Spee	eed: 8 Gusts: Weather Condtions at Accident Site: Visual Cond							ond	itions				
Visibility (R	RVR): Ft.	Visibility	(RVV)		SM	Intensity	of Precipi	itation:					
Restriction	Restrictions to Visibility: None												
Type of Pre	ecipitation: None												
Accident	Information												
Aircraft Damage: None Aircraft Fire: None Aircraft Explosion None													
Classificati	ion: U.S. Registered/U.	.S. Soil											
- Injury Sur	mmary Matrix	Fatal	Serious	Minor		None	TOTAL						
First Pil	lot					1		1					
Second	d Pilot					1		1					
Student	it Pilot							7					
Flight Ir	nstructor							7					
Check F	Pilot							7					
Flight E	Engineer							7					
Cabin A	Attendants		1					1					
Other C	Crew							7					
Passen	ngers					1		1					
- TOTAL A	ABOARD -		1			3		4					
Other G	Ground Ground							7					
- GRAND	O TOTAL -		1			3	4	4					
			<u>'</u>		'								

National Transportation Safety Board

FACTUAL REPORT AVIATION

Occurrence Date: 02/08/2002

Occurrence Type: Accident

Δ	dm	inis	trativ	r⊵ Int	f∩rm	ation
$\overline{}$	ulli	บบอ	uauv			alioi

Investigator-In-Charge (IIC)

Arnold W. Scott

Additional Persons Participating in This Accident/Incident Investigation:

James P Clayville Air Safety Inspector- Avionics FAA- Flight Standards District Office 26805 E 68th Ave. Suite 200 Denver, CO 80249